



## Avaya 3730 DECT handset release 2.1.4 Edition 6 Readme

---

This file is the Readme for the Avaya 3730 v2.1.4 Edition 6. This file describes the contents of the software distribution package.



Please refer to the Advisements in this file for important information prior to deploying this software.

### Release history

---

Release	Edition	Date	Description
3730 v2.1.4	6	July 10 <sup>th</sup> , 2017	Initial 3730 release for Edition 6

### Additional DECT updates

---

This release is part of the DECT solution maintenance release including also the following updates:

Product	release number
37xx Handsets	4.5.2
373x Handsets	2.1.4
IP-DECT IPBS1	10.0.6
IP-DECT IPBS2	10.0.6
IP-DECT GW	10.0.6
IP-DECT DB1	R3F
IP-DECT DB1 IE	7.0.13
AIWS II	4.5.1
WinPDM	3.13.2
BS3x0	R7C

Please refer to Avaya support site <http://support.avaya.com/> for further information

Copyright Avaya 2017

All rights reserved

## Avaya Aura® Compatibility

---

The Avaya 3730 v2.1.4 software is supported with these latest releases of:

- Avaya Aura® Communication Manager 6.3.15.1 (Service Pack 15.1) - 03.0.124.0-23382
- Avaya Aura® Communication Manager 7.0.1.1.1 (Service Pack 1.1) - 00.0.441.0-23384
- Meeting Exchange 6.2
- Meeting Exchange 6.2.3

## Avaya 3730 2.1.4 Package Content

---

The Avaya 3730 2.1.4 package contains all the files necessary to upgrade Avaya 3730 handsets to 2.1.4 software.

- **3730\_v2.1.4.pkg** software package including the firmware (included in the 3730\_v2.1.4\_EndCustomer folder)
- **Downloadable\_languages\_3730.zip** – language files.
- **Translation\_Tool\_3730.xls** - Tool to create additional language files to upload to the handset
- **Company\_Phonebook\_Tool\_v9.zip** - Tool to create a company phonebook for uploading in the handset
- **3730\_Handset\_ReleaseReadme\_SW\_Version2\_1\_4.pdf** – this release notes document

## New Features in release 2.1.4

---

The new handset 3730 is introduced for the first time with Edition 6.

## Unsupported features in release 2.1.4

---

The local phonebook tool has been deprecated in prior releases. It has been replaced by import/export functionality from the device manager.

## **Advisements with Avaya 3730 2.1.4 software**

---

### **None**

## **Resolved issues in Avaya 3730 release 2.1.4**

---

First release - no previous known issues

## **Unresolved issues in Avaya 3730 release 2.1.4**

---

There are no known issues with the new handset of 3730

## **2017 Avaya Inc. All Rights Reserved.**

---

### **Notice**

While reasonable efforts were made to ensure that the information in this document was complete and accurate at the time of printing, Avaya Inc. can assume no liability for any errors. Changes and corrections to the information in this document may be incorporated in future releases.

### **Documentation disclaimer**

Avaya Inc. is not responsible for any modifications, additions, or deletions to the original published version of this documentation unless such modifications, additions, or deletions were performed by Avaya.

### **Link disclaimer**

Avaya Inc. is not responsible for the contents or reliability of any linked Web sites referenced elsewhere within this Documentation, and Avaya does not necessarily endorse the products, services, or information described or offered within them. We cannot guarantee that these links will work all of the time and we have no control over the availability of the linked pages.