



ELECTRONICS

## TECHNICAL BULLETIN

Date: 09/25/01  
NO.: 2001-13

### **TITLE: Software update for DCS Compact and 50si**

---

The purpose of this bulletin is to inform our dealers of issues found in the following software versions:

DCS Compact version 2.6 dated 01.06.01  
50si version 1.5 dated 01.05.21

If you have experienced any of the problems listed below on the DCS Compact version 2.6 or the 50si version 1.5, please contact Technical Support for updated software. The new software for the DCS Compact is Version 2.6 dated 01.09.01 and 50si version 1.5 dated 01.09.01. All orders shipped on or after September 26, 2001 will be shipped with the new software versions.

1. Setting ring over page in the operator group will lock up the page port. This only occurs when the SVMi-4 is installed in the system.
2. When using MMC 723 to assign default key assignments and there are a mix of DCS and Falcon keysets, the program will override the Falcon system wide button assignments.
3. Keyset LEDs will light randomly.
4. In MMC 807, the "MIN RX" setting will not work correctly with the Falcon keysets.
5. Internal paging volume on keysets will drop to the lowest level and remain at that setting until the telephone system is reset.

*If you have any questions about this or any other Technical bulletins please contact Technical support by phone 1(800) 737- 7008 or by email [techsupportmiami@sta.samsung.com](mailto:techsupportmiami@sta.samsung.com)*

---