



ELECTRONICS

TECHNICAL BULLETIN

Date: 1/16/02

NO.: 2002-04

TITLE: DCS 50si Reserve power battery connector

The purpose of this bulletin is to inform you of a misprint in the DCS 50si technical manual. Figure 7-16 in the installation section shows the color of the wires reversed. The black wire should be on the left side and the red wire should be on the right side. Attached is the page that you should replace with the current page in your manual if it is dated earlier than December 1998.

The attached page can be found under bulletin labeled "Tech Bull 2002-04fig".

If you have any questions about this or any other Technical bulletins please contact Technical support by phone 1800 737 7008 or by email techsupportmiami@sta.samsung.com
