

IP Office Technical Tip

Tip Number:	267
Release Date:	15 July 2014
Region:	GLOBAL

IP Office 9.0 Service Pack 3 Critical Patch

This Technical Tip is to inform customers about the availability of a Critical Patch (CP) for IP Office 9.0 Service Pack 3, released 19th May 2014. The CP resolves a number of issues identified in this release:

JIRA Number	Description of Issue
IPOFFICE-66213	Server Edition Restart - related to third party IVR interaction
IPOFFICE-63280	Intermittently calls to third party SIP extensions seem to be losing CTI Monitoring
IPOFFICE-68181	System Restart - Line Appearances configured before Call Appearances, 1400 telephone places call on hold
IPOFFICE-67633	System Restart - Calls to a busy or logged off user or group without queuing, overflow or voicemail enabled
IPOFFICE-68834	System Restart - Held calls and Bridged Appearances configured on second page of buttons for 9608

The CP (9.0.3.16.2) consists of new binary files for IP500, IP500V2 and RPM file for Server Edition systems. It also includes the resolution for the Devlink issue documented in IP Office Technical Tip 266. Avaya recommends that customers experiencing these issues apply this CP.

The CP can be found in the IP Office "9.0.X" Download section of the Avaya Support web site:

http://support.avaya.com

The CP will be incorporated into IP Office 9.0 Service Pack 4 due for release August 2014

Issued by: Avaya SMEC Customer Product Engineering Support

Contact details:-EMEA/APAC

Email: gsstier4@avaya.com

NA/CALA

Email: IPONACALAT4@Avaya.com

Internet: <u>http://www.avaya.com</u> © 2014 Avaya Inc. All rights reserved.