



Bulletin No. 177_4_14k_Hardware

May 1, 2008

Hardware Requiring V4.14k Software or Higher

Due to changes in suppliers of various components and chips sets these cards/modules required new PCB design. In the next 30 days to 6 months these cards will be introduced on a running change basis. As the current supply sells out, the replacement cards will be introduced. They are equivalent to the current cards in all functionality and capacities. However, they require Main System Software V4.14k or higher to be compatible with the new chip sets.

CARD/MODULE	PRODUCT CODE
OS MP40	KPOS74BMPM/XAR
OS LP40	KPOS74BLP/XAR
OS CRM	KPOS74BCRM/XAR
OS 8SLI2	KP-OSDB8S2/XAR
OS 8COMBO2	KP-OSDB8H3/XAR
OS 8TRUNK2	KP-OSDB8T2/XAR
OS 16TRK	KP-OSDB16T/XAR
OS PLIM2	KP-OSDBPL2/XAR

A yellow sticker will be applied to the unit carton and a printed note will be inside the box to remind you of this change.

If there are any questions regarding this notice please contact your Regional Sales Manager or Samsung Technical Support Representative via email at BCS.Support@samsung.com.