

Bulletin No.: 205_Wireless_Software_Update

November 5, 2009

Samsung OfficeServ Wireless Handset New Software Release

Samsung Telecommunication America is pleased to announce a new software version for the OfficeServ Wireless SMT-W5100E handset. This new software version adds some new features and fixes some bugs.

NEW RELEASE SOFTWARE

Beginning 11/05/09 all SMT-W5100E handsets shipped from STA warehouse will have new software.

Product	Version	Date Code
SMT-W5100E 802.11g Handset	V 01.08.04	09-22-2009

This new software is available for download on the Samsung's GSBN website at <http://www.samsunggsbn.com> under Communication → Technical Support → Downloads → Released Software.

The OfficeServ 7000 main system software should be 4.30a or higher. This software version is not supported on the OfficeServ 100 or OfficeServ 500 systems.

SOFTWARE ENHANCEMENTS AND FIXES



SMT-W5100E 802.11g Wireless Handset **V01.08.04, 09-22-2009 (New Released Version)**

- Fixed bug that couldn't work in WEP key with two 00s in HEX mode.
- Fixed bug that handset couldn't automatically re-register if powered off and then on if previously registered in SIP mode and standard DHCP mode.
- Fixed bug that the revised members of conference group (when changed in MMC 118) would reflect to the handset.
- Fixed bug that user could return external calls from call log list when handset was registered in non-SIP mode.

Samsung Telecommunications America
Business Communication Systems
1301 East Lookout Drive
Richardson, TX 75082

Samsung OfficeServ Wireless

- Fixed bug that handset displayed double image. This occurred during registration when the handset was in non-SIP mode and the wireless access point failed to respond. The handset display no longer overlaps between menu and registration animation during registration.
- Added error checking function for uncompleted IP address. Ex. 192.168.1.
- Added error display message when users select the unassigned zone in Page menu.

V01.07.01, 01-14-2009 (Existing Version)

- Fixed ring continuously problem. When handset is out of range, ringer will be timed out in 15 seconds.
- Fixed “normal clear registration” bug in non-SIP mode.
- Fixed bug that if the incoming call occurred while the alarm is ringing, the phone was ringing on the idle screen.
- Added function that can decrease the ringer volume during the first 3 seconds after receiving incoming calls.
- Added function to turn on the backlight for a few seconds, every 1 minute, until the user checks the missed call.
- Added function to allow handset software to be upgraded through handset web page to the FTP server.

DOCUMENTATION

A Quick Reference Document is also available for download on the Samsung's GSBN website at <http://www.samsunggsbn.com> under Communication → Technical Support → Downloads → Technical Manuals.

TRAINING

Instructor Led OfficeServ Wireless (Course # 3020-01-IL) training classes are available through the training department. For a list of available classes and seat availability, download the current Instructor Led training schedule from the GSBN website under Communication → Training → Downloads → Schedules. We highly recommend you to obtain Wireless Certification before any OfficeServ Wireless installation.

If you have any questions regarding this product Bulletin, please contact your Regional Sales Manager, or Sales Engineers at the number provided below, or send an email to BCS.Sales@samsung.com.