



Technical Bulletin

TITLE: DCS Compact MISC Card
DATE: May 14, 1998
ISSUED BY: TECHNICAL SUPPORT DEPARTMENT

BULLETIN NO.: TB 9804
NO. OF PAGES: 1 of 1

There is some confusion regarding the serial cable connections on the MISC and MISC2 cards in the DCS Compact.

The diagrams in the DCS Compact Installation Section, figures 7-7 and 7-8, dated June 1995, should be changed to reflect the following pin connections:

Figure 7-7

PIN CONNECTIONS FOR MISC CARD TO PERSONAL COMPUTER




Figure 7-8

PIN CONNECTIONS FOR MISC CARD TO MODEM

