



ELECTRONICS

TECHNICAL BULLETIN

Date: April 12, 2000

NO.: 2000-04

TITLE: DCS 50si RELEASE 1.2

Orders for software as of April 11, 2000 will contain the version DCS 50si Release 1.2. Release 1.2 has been introduced to address the following issues:

BRI External Call Forward

An incoming call will be disconnected if all of the following conditions occur:

- 1/ an incoming call on a BRI circuit is set to ring a station group.
- 2/ the call is transferred from the group to another station.
- 3/ the other station is set to be external call forward via another BRI circuit.
- 4/ the call is answered by the external party.

Release 1.2 resolves the issue.

BRI Trunk to Trunk Transfer

The call will not be connected if all of the following occurs:

- 1/ an incoming call on a BRI circuit is answered at a station.
- 2/ the station user performs a blind external transfers to another BRI circuit. (If the station user performs a "Supervised Transfer" the caller will be successfully connected when the party answers)

Release 1.2 resolves the issue.

Important Note

Release 1.2 is compatible with the current PCMMC, version PC500113.

If you have any questions about this or any other Technical Bulletins please contact Technical Support by phone: 1800 737 7008 or by email: techsupport@sta.samsung.com.