

TITLE: DSP ON DCS COMPACT

DATE: JUNE 5, 1995

ISSUED BY: PRODUCT DEPARTMENT

BULLETIN NO.: 034-DCSC

NO. OF PAGES: 1 of 1

Engineering has pointed out to us that we have incorrectly listed in our documentation the number of DSP circuits on the MISC 1 and MISC 2 cards.

In the General Description Section of the DCS COMPACT Technical Manual, the following two corrections have been made:

- 1. On page 1-3, the paragraph titled "Switching," has been corrected to indicate "an additional four DSPs are added when a MISC card is installed" and "the system contains a total of eight DSP channels when fully expanded."
- 2. Item E on page 2-2 under "2.4 INTERFACE CARDS" has been corrected to indicate four DSP circuits.

These pages are corrected and included in the next DCS COMPACT Technical Manual Update that will be on its way to you shortly. Please note that these two errors also appear in the General Description booklet. They will be corrected in the next reprint.