

TITLE: SPEED DIAL ON DCS COMPACT

BULLETIN NO.: 043-DCSC

DATE: AUGUST 25. 1995

NO. OF PAGES: 1 of 1

ISSUED BY: PRODUCT DEPARTMENT

This bulletin is issued to clear up some confusion relating to the number of speed dial numbers available on the DCS COMPACT.

The following chart outlines the possibilities.

1	RAM Pack 1 + Basic Software Package	500 speed dial numbers
2	RAM Pack 1 + Caller ID Software Package*	500 speed dial numbers
3	RAM Pack 2 + Basic Software Package	500 speed dial numbers
4	RAM Pack 2 + Caller ID Software Package	1500 speed dial numbers

^{*}This configuration will cause all keyset displays to default with [2XX: NO EXPRAM!]. System operation is not affected.

NOTE: This copy of Product Bulletin 43 corrects a typographical error present in earlier copies of Product Bulletin 43. In Item 2 of the table above, RAM Pack "2" was incorrectly indicated rather than RAM Pack "1." We apologize for the typo and for any inconvenience that it caused you.