

TITLE: KDB-SLI AND HEADSETS

DATE: OCTOBER 10, 1995

ISSUED BY: PRODUCT DEPARTMENT

BULLETIN NO.: 046-DCSZ

NO. OF PAGES: 1 of 1

This bulletin is to advise installers that DCS keysets with V1.0 ROM cannot support HEAD-SET MODE and KDb-SLIs at the same time. When a DCS keyset with V1.0 ROM is in HEADSET MODE and has a KDb-SLI, there is no dial tone on the SLI device connected to the KDb-SLI.

The new LCD 12B keyset was developed much later than the other keysets and therefore supports KDb-SLIs and HEADSET MODE because it has V1.1 ROM.

A new ROM version to replace V1.0 was to be available last April but is delayed. Until further notice, use an LCD 12B keyset to use KDb-SLIs and HEADSET MODE simultaneously or install the KDb-SLI in another keyset that will not use a headset.