



Bulletin No. 138_iDCS_16

December 8, 2005

iDCS 16: Software Version 2.05

Samsung Telecommunications America is pleased to announce the release of software version 2.05(05.09.27) for the iDCS 16. This new version of software includes several problem corrections. Product shipping from Samsung starting December 8, 2005 will include software version 2.05.

Many dealers have already installed this version of software and assisted us with field trials in confirming the software is stable. Samsung would like to extend our sincere appreciation to all who helped in the effort.

SOFTWARE COMPATIBILITY TABLE

	ROM	OSM Launch Pad	OSM	AA (pgm)	AA (msg)
Version	V2.05	V1.03	V3.04	V1.0	V1.0
Date	050927	050921	050907	981029	980921

FIXES

MMC 723 Data Memory

The data in MMC 723 was not being held in memory during a power cycle. This has been corrected.

NND Key During Incoming CO

When the NND key is pressed during an incoming ringing call, the CID information should toggle the display from number, to name, to time and date during the ringing call. This was not working. This has been corrected.

MMC 604 Internal Page Group via OSM

When using OSM to add members 201 thru 210 sequentially in the all page (*) column, the data was not being saved correctly. Member 1 is displayed as 384, and all other members in the internal all group is displayed as station 201. This has been corrected with the latest OfficeServ Manager (OSM) version.

Samsung Telecommunications America
Business Communication Systems
1301 East Lookout Drive
Richardson, TX 75082

800-876-4782

Page 1 of 2

www.samsung.com/bcs

iDCS 16 Software Version 2.05

MMC 600 and Next Port Assignment via OSM

When trying to enter a station group in the overflow port (next port), OfficeServ Manager program will not accept the station group entry. KMMC does not have the problem. This has been corrected with the latest OSM version.

OFFICESERV MANAGER

A compatible version of the OfficeServ Launch Pad (PCMMC) software version 1.03(2005.09.21) and OfficeServ Manager, version 3.04(2005.09.07) for the iDCS 16, version 2.05(2005.09.27) is available for programming via a PC. This version of OfficeServ Manager is backwards compatible with earlier versions of system software. The latest version of OSM software patch can be downloaded from the Samsung eCommerce web site.

OSM will allow you to program the iDCS 16 on site or remotely via the serial connection. A new OfficeServ Manager module is available for programming the iDCS 16. This module is installed automatically when installing the new OSM Launch Pad v1.03 (2005.09.21) or can be added to an existing OSM Launch Pad by simply downloading the iDCS 16 OSM module. The iDCS 16 module is version 3.04 (05.09.07). The updated OSM Module is available at <http://ebiz.samsungusa.com>, under Technical Support, then click on Download Software.

When using OfficeServ Manager software, some MMCs may display on the PC screen that do not apply to the version of software that is running in the DCS system. These MMC entries are reserved for future use. When this occurs, an error message of: “NO CORRESPONDING DATA” will appear on the PC screen.

If you have any questions regarding this Product Bulletin, please contact Technical Support at 800-737-7008 or via email at BCS.Support@samsung.com.