Bulletin No.: 223_SMT_i_Series_Software_Update_REVISED September 1, 2010

Samsung OfficeServ™ SMT-i Series Phones New Software Release



Samsung Telecommunication America is pleased to announce a new software version for the OfficeServ SMT-i Series phones. This new software version adds support for <u>Spanish and French</u> languages and fixes known bugs.

NEW RELEASE SOFTWARE

Product	Version	Date Code
SMT-i3105	V 01.33	July-22-2010
SMT-i5210	V 01.11	July-22-2010
SMT-i5230	V 01.11	July-21-2010
SMT-i5243	V 01.66	July-28-2010

This new software is available for download on the Samsung's GSBN website at http://www.samsunggsbn.com under Communication → Technical Support → Downloads → Released Software.

The OfficeServ 7000 main system software should be 4.46d or higher. This software version is not supported on the OfficeServ 100 or OfficeServ 500 systems.

Samsung Telecommunications America Business Communication Systems 1301 East Lookout Drive Richardson, TX 75082

Samsung SMT-i Series New Software Release

SOFTWARE ENHANCEMENTS AND FIXES

		SMT-i3105	SMT-i5210	SMT-i5230	SMT-i5243
1.	Added Spanish and French language support.	✓	✓	✓	✓
2.	Fixed bug that headset volume reset to the previous setting.	✓	✓	✓	
3.	Improved clarity of warning message when using "Busy/No Ans" call forward feature.	✓	✓	✓	
4.	Allowed the 'P' or 'p' pause code in the call forward setting.	✓	✓	✓	✓
5.	Fixed VLAN error.		✓	✓	
6.	Fixed phone book entry error.		✓		
7.	Fixed bug that disables headset key while in background music mode (BGM).		✓		
8.	Fixed 802.1x MD5 authentication issue.				✓
9.	Fixed display issue that date gets truncated.				✓
10.	Adjusted the ring volume to the same as other SMT-i models.				✓
11.	Reduced the time to process the dialed digits.				✓
12.	Fixed bug in extension login mode. If the phone has a camera connected to it, logout and login will preserve the video mode. Previous bug will put phone into the voice only mode.				✓

If you have any questions regarding this notice, contact your Regional Sales Manager, or your Customer Service Representative at the number provided below, or via email at BCS.Sales@samsung.com