



Bulletin No.: 2010-01

July 26, 2010

UNICARD with MP20-S Warning

As there has recently been one or two Technical Support Calls generated by not observing the restriction for using older versions of UNI Card, on the MP20-S, this is a reissuance of a bulletin released in January 2010. This therefore, notifies dealers to not use older versions of UNI Card with the MP20-S processor.

UNI Cards produced before September 2009 will need to be upgraded for proper operation with the MP20-S processor. However these old versions of UNI Card will work OK with MP10, MP10A. (Note: MP20 processors do not support UNI Card at all).

Check out the UNI Card. If it's V05 or greater it's OK.

Check the Firmware:
MMC 859 / IT 2.2.0
"EPLD Version" Should be V05 or Greater

DIP Switch	
Option Board	
EPLD Version	V05
PCB Version	V01

Visual Inspection

Look For a Sticker
Upgraded Cards Will Have A Sticker:

Sticker Should Say:

UNI
V05
007E



If you need to have an older version of card upgraded, then request a repair RMA via GSBN and send it in for a free upgrade.

If you have any questions about this or any other Technical Support bulletins please contact Samsung Technical Support by phone at 1-800-737-7008 or by email at: BCS.Support@Samsung.com