



Bulletin No.: 186\_OS\_100\_v2\_76b

January 12, 2009

## OfficeServ 100 Software Version 2.76b Release

Samsung Telecommunications is pleased to announce the general availability of software version 2.76b for the OfficeServ 100 system.

### NEW FEATURES

There are no new features in version 2.76b for the OfficeServ 100 system.

### BUG FIXES

- 1. Ring Plan Routing Issue with SVMi:** When using SPNet with Centralized SVMi, if the switch Ring Plan was changed causing incoming calls to ring in another node, the SVMi message waiting lamp feature would not work. *This has been fixed in version 2.76b.*
- 2. 32 BUTTON ADD ON MODULE:** On the OfficeServ 100 System, using the 32 button add-on module in the stand alone mode would not allow the user to use the ANS/RLS button to answer the call. *This has been fixed in version 2.76b.*
- 3. 8 BTN SET PROGRAMMING:** The OfficeServ 100 System would not allow the 8 button keyset user to log into the programming. *This has been fixed in version 2.76b.*
- 4. PRI NAME DELIVERY:** On the OS-100 System using PRI trunking, inbound calls to Analog Sets would not deliver the CID Name being sent from Telco. *This has been fixed in version 2.76b.*

### SOFTWARE COMPATIBILITY VERSION AND DATES

Product	Software Version	Production Date
OfficeServ 100	V2.76b	12/08/2008

Samsung Telecommunications America  
Business Communication Systems  
1301 East Lookout Drive  
Richardson, TX 75082

800-876-4782

[www.samsunggsbn.com](http://www.samsunggsbn.com)

## OfficeServ 100 Software Version 2.76b Release

	MCP-1	SP100	TEPRI	TERPla	MGI-3	MGI-16	OSM
Version	V2.76b	V1.09	V1.07	V4.25	V3.61	V1.24	3.75
Date	12/08/08	04/17/08	11/27/04	11/27/08	10/10/06	11/27/08	03/21/08

### DOCUMENTATION

There is no documentation changes required with this new software.

### GENERAL AVAILABILITY

Beginning January 12<sup>th</sup>, 2009 all OfficeServ 100 systems shipped from STA warehouse will have V2.76b software.

If you have any questions regarding this product Bulletin, please contact your Regional Sales Manager, or Sales Engineers at the number provided below, or send an email to [BCS.Sales@samsung.com](mailto:BCS.Sales@samsung.com).